



## TeamConnect Bar

All-In-One Device for Collaborations Rooms

### Firmware Update

- The TeamConnect Bar firmware update requires the Sennheiser Control Cockpit software:  
[www.sennheiser.com/control-cockpit-software](http://www.sennheiser.com/control-cockpit-software)

### Firmware version 1.0.3 - Release Date 2024-07-04

#### Bugfix

- The issue preventing the use of Dante on TC Bar M in Single Domain Mode has been fixed.

#### Known Issues

- When connecting both ports of the TC Bar M to a common switch, there is a risk of creating loops. Make sure your TC Bar M is always connected to two different networks that do not run via a common switch. For more details see chapter [Network Loops](#) of the user manual.
- When manually adding a TC Bar to the Control Cockpit, the TC Bar can no longer be deleted unless it is offline.
- If the IP of the TC Bar is greyed out or the TC Bar cannot be controlled via Control Cockpit, the control service may not be accessible, a restart of the TC Bar is recommended.
- The setting of the sound profile in Control Cockpit has no influence on audio streaming via Bluetooth (A2DP profile).
- If you deactivate the Dante protocol via Control Cockpit, the TC Bar must be restarted to completely terminate the audio stream.

### Previous Releases

#### Firmware version 1.0.0 - Release Date 2024-06-10

- Initial firmware release v1.0.0 for TeamConnect Bar S and TeamConnect Bar M.