Sennheiser Profile Wireless V4.0.3

Release Date: 19.11.2024

System Requirements

Windows
Windows 10 32 Bit
Windows 10 64 Bit

Mac OS
Mac 11.0 Big Sur

Download

www.sennheiser.com

Improvements and fixes

- Fixed " If you format the TX memory with windows and then start recording, there is a possibility that the recording files will be lost when you reconnect the device to windows again"
- Fixed "There is a chance that the RX Device screen display the update page randomly"
- Fixed "There is a chance that the RX Device freezes when repeatedly plugging and unplugging headphones"
- Fixed "There is a chance that the RX Device will not charge in the charging bar, when repeatedly enters and exits the charging bar,"
- Optimize "RX Device state of charge icons while charging"

Known Issues

- RX Device Main Screen: Double tapping to start recording is not split into TX1 and TX2 areas to be recognized as double tapping. If you tap once on the TX1 area and then once on the TX2 area, this will be recognized as a double tap and recording will start on the TX2 device (and vice versa).
- For updating the RX Device: the TX Device must be switched OFF or disconnected from RX Device

Previous releases

Release Date: 01.10.2024

Sennheiser Profile Wireless V4.0.0

New Features

- Initial Release with all Features